



## King's Harbour Master Clyde

### LNTM No 04/25

#### GARELOCH - NAVIGATION BEACON 2N UNRELIABLE

#### Notice

Mariners are advised that Aid to Navigation (AtoN) Beacon 2N in position 56 00.672N, 04 47.712W is currently unreliable.

#### Details:

- **AtoN Name/ID:** A4423 Gareloch. Rhu Narrow. Limeklin Point No 2N. Dir Lt 295 deg (A)
- **Location:** 56 00.627N, 04 47.712W
- **Nature of Issue:** Light is currently not operating to character and is unreliable.
- **Impact on Navigation:** Mariners should exercise caution when navigating in the vicinity of this AtoN as it is unreliable.

#### Actions Taken:

- The maintenance contractor has been notified and is currently addressing the issue.
- The General Lighthouse Authority (GLA) has been informed, and further updates will be provided as necessary.

#### Measures to be Taken:

- Mariners are advised to use alternate navigational aids and exercise heightened vigilance.

#### Further Information:

- Updates will be issued through subsequent Local Notices to Mariners (LNTMs) as the situation progresses.
- For more information, please contact KHM Clyde Harbour Control on 01436 674321 (Opt.1, Ext.3555)

#### Extant LNTMs:

- Next LNTM: 05/25.
- The following KHM Clyde Local Notices to Mariners remain in force at the time of publication: 01/25, 02/25, 03/25, 04/25, 05/25.

Wednesday 01 Jan 2025

Nick Groves  
Deputy King's Harbour Master Clyde