



## King's Harbour Master Plymouth

**LNTM No 013/25**

**PLNTM 013\_25 JUPITER POINT DIRECTION**

### **PLYMOUTH LOCAL NOTICE TO MARINERS 013/25**

#### **JUPITER POINT - DIRECTION**

1. This notice is a direction by the King's Harbour Master (KHM) Plymouth pursuant to the Dockyard Port of Plymouth Order 2020.
2. Due to issues with the pontoon mooring arrangements at Jupiter Point (50°23.400'N 004°13.750'W).
3. Mariners are directed to keep a safe distance and reduce speed as to keep wash to a minimum when transiting between Sandacre Buoy (50°23.549'N 004°13.423'W) and Antony Buoy (50°23.564'N 004°13.933'W).

Wednesday 01 Jan 2025

R Giles  
King's Harbour Master  
Dockyard Port of Plymouth